



Service Bulletin

Date: February 7, 2003

Product Line: Snowmobile

Bulletin No: 2003-1-33

Subject: Snow Flap Reinforcement

Affected Models / VIN:

All 2003 Firecat 700 cc Models

Condition: It has been determined that under certain conditions, the snow flap on the affected models may be drawn into the tunnel causing possible damage to the snow flap and also preventing snow from helping cool the rear heat exchanger.

Solution: Install Snow Flap Update Kit (p/n 0637-253) per instructions in the kit.

■ **NOTE:** Snow Flap Update Kit (p/n 0637-253) is a reinforcement kit designed to prevent the existing snow flap from being drawn into the tunnel.

Parts: Order an appropriate number of Snow Flap Update Kit (p/n 0637-253) through normal parts-ordering channels. Your dealership Parts-Account will be charged and then credited upon receipt of a Warranty Claim Request form.

Warranty: A labor allowance of 0.2 hr will be paid per affected snowmobile.

CatTracker Claim: Enter BS200333 in the Complaint section.

Manual Claim: Enter 0333 in the Complaint section.



Printed in the U.S.A.



®™ Trademarks of Arctic Cat Inc., Thief River Falls, MN 56701



0203