





SERVICE 		8
		B0000018

English 1 (1)

SB, 345, 350, 351, 346 XP, Chain tensioner, 2000-05

The chain tensioner has been modified to eliminate the risk of it unmeshing and is now a single unit.

New Ref. No.	Description	Excl. Ref. No.	Remarks
537 07 12-01	Chain tensioner	503 86 91-01	

Introduced in production from serial number:	345	994800451
	350	994702251
	351	995000006
	346 XP	994500081

****compl 537 07 12-01**

