





SERVICE 		2
		B0200056

English 1 (1)

SB, 18 H, Cylinder and piston, 2002-08

The 18H hedge trimmer has been manufactured with both 18 and 21 cc cylinders. This has meant that customers occasionally order the wrong parts. The correct part numbers are given below.

New part no.	Description	Excl. part no.	Remark
530 06 96-13	Piston 18 cc		Diameter 29.5 mm
530 06 96-14	Cylinder 18 cc		
530 02 99-24	Piston ring 18 cc		
530 06 96-21	Piston 21 cc		Diameter 32 mm
530 06 96-19	Cylinder 21 cc		
530 03 64-04	Piston ring 21 cc		