





SERVICE 		4
		B0300061

English 1 (2)

SB, 395, Tank valve, 2003-11

Two-way tank valve introduced on the above models.

The two-way valve has the following features:

- Controlled opening pressure in both directions, which prevents excess of pressure or vacuum developing in the fuel tank and impairing engine operation. This also reduces the likelihood of petrol leaks.
- More resistant to clogging with dirt in comparison with “earlier” version of tank vent.
- More resistant to icing up during winter operation compared with “earlier” version of tank vent.
- Venting pressure 150–400 mbar.
- Opening pressure under vacuum, max. 115 mbar.

New part no.	Description	Excl. part no.	Remark
537 33 81-01	Tank vent assy.		
537 09 93-01	Connector	503 60 04-01	*
537 09 22-01	Tank valve	501 87 31-01	*
537 19 01-01	Adapter		
501 76 83-05	Hose 105 mm		**
504 35 72-01	Sintered plug		

* Still fitted to other models



** Only fit the hose between the valve and filter bend on saws without carburettor heating.

Introduced from serial number: 395 033900111

NOTE!

Do not use compressed air to clean or pressure test the valve, as this will damage its internal components.



SERVICE 		4
		B0300061

English 2 (2)

