



<b>Service Bulletin</b>	<b>B0301902</b>
	<b>2003-10</b>

English 1(1)

## SB, 136/141

### Adjustment screws for carburetor, 2003-10

A carburetor without limiter caps for the L- and H- speed jets has been introduced on the above models.

The carburetor has a new type of screw head for the L- and H- speed jets (see picture). The adjustment screws are grooved on the outer edge and will not have a slot in the head.

To simplify the adjustment of the carburetor a special service tool is available.

New part no.	Description	Excl. part no.	Remark
530 03 55-60	Adjustment screw driver		

