

IMPORTANT!

When changing the cylinder Ref. No. 503 53 68-01 (with 4 mm metric thread) on a saw with lower serial number than above mentioned, the carburettor support Ref. No. 503 59 20-01 must also be mounted. Also a larger carburettor screw Ref. No. 503 49 69-01 (model 268) must be used. See illustration 2.

NOTE!

Carburettor support Ref. No. 503 59 20-01 cannot be used on the crankcase that has been changed. In order to simplify the spare parts handling, we have decided to enclose the following parts with cylinder compl. Ref. No. 503 53 68-01. We will only do this for a certain period until everybody has acknowledged this change.

503 49 69-01	Carburetor screw M4 x 80	2 pcs
734 11 46-01	Washer	2 pcs
725 52 91-55	Screw	2 pcs
503 59 26-01	Clip	2 pcs
503 59 20-01	Carburettor support	1 pc
501 86 21-02	Gasket	1 pc

When changing cylinder on "older" crankcases:

- Carburettor support Ref. No. 503 59 20-01 is already mounted. Change the carburettor screws (5 mm metric thread) to the screws (4 mm metric thread) Ref. No. 503 49 69-01 with plastic cover. Note! Leave the fibre sleeves in the carburettor. Note! For special markets only.
- No carburettor support Ref. No. 503 59 20-01 is mounted.

Change the carburettor screws (5 mm metric thread) to the screws (4 mm metric thread) with plastic cover Ref. No. 503 49 69-01. Mount the carburettor support Ref. No. 503 59 02-01 according to the ill. The support is fastened in the crankcase by enlarging the existing holes for the stop switch and the heated handle switch to \varnothing 3,1 mm. Then thread the holes to metric 4.

