



<p>SERVICE</p> 		<p>15</p> <hr/> <p>X 90.115-26</p>
---	--	---

IRON HORSE

A tensioning wheel bearing with a new type of rear drive wheel shaft has been introduced on serial nos. 0301399 onwards.

The new shaft is circular in section where it meets the ball bearing inner ring, in order to prevent dirt entering the bearing housing. On machines with the old type of shaft the sealing rings on the ball bearing become damaged when dirt enters the bearing housing. This results in the ball bearing wearing out unusually fast.

A plug has also been fitted to the hole in the bearing housing.

- Nyttillkomna artiklar:
- 1 531 00 14-90 Axel
 - 1 531 00 00-21 Plugg
 - 1 531 00 00-22 Bricka
 - 1 531 00 03-44 Mutter

- Borttagna artiklar:
- 531 00 00-18 Bricka
 - 721 62 16-01 Saxpinne
 - 531 00 01-94 Lasring
 - 531 00 00-11 Axel

