





SERVICE 		7
		X 91.024-26

RIDER 650-6

A new design of the engine pulley is introduced from the model -90 to -91. The washer is no longer welded inside the shaft tube. It is loose under the engine pulley.

Parts must not be mixed between the models -90 to -91.

When changing to a new engine pulley 533 31 53-62, the screw 533 14 27-64 (7/16-20 x 3,25") washer 533 05 64-31 and key 533 30 31-51 should be mounted at the same time.

New Ref. No.	Description	Excluded Ref. No.	Remark
533 31 53-62	Engine	533 30 50-07	Is excluded
533 30 31-51	Key	533 03 32-00	Remains as a spare part
533 05 64-31	Washer	533 12 03-83	Remains as a spare part
533 14 27-64	Screw	533 12 35-67	Remains as a spare part

