

## Model Master 43RC

As from 1996 models the cable can be separated thanks to a quick connector by the charger plug. This is to ease changing charger plugs if necessary.

The following applies to 1995 models and older:

If the charger plug needs to be changed on older cables (95 and earlier), the new plug is used with a connection strip.

1. Cut off the defective charger plug.
2. Strip the three cable ends.
3. Fit these to the connection strip.
4. Cut off the quick connector from one 535 01 59-01.
5. Strip the three cable ends.
6. Fit these to the connection strip.

