





SERVICE 		11
		B9800039

SB, 225 H, Support plate, 1998-10

We have noticed that there can be excessive friction between the corrugated support plate and the lower blade. To eliminate this a flat support plate has been developed. This can be fitted to machines with serial nos. 8010001 onwards. The support plate has been introduced from serial no. 83330001.

New ref. no.	Description	Excl. ref. no.	Remarks
503 85 00-03	Support plate 60 cm	537 01 29-01	
503 85 00-04	Support plate 75 cm	537 01 29-02	
503 79 38-07	Cutter bar 60 cm	503 79 38-05	complete
503 79 38-08	Cutter bar 75 cm	503 79 38-06	complete

The earlier corrugated support plates, 503 76 97-03 and 503 76 97-04, will still be available as spare parts for machines with serial nos. up to and including 7529999.

Note! If support plate 503 85 00-03 or 503 85 00-04 is fitted to older machines, the ignition system 503 84 32-01 with speed limiter must also be fitted. Otherwise the blades may not stop quickly enough to meet authority requirements.