



Service Advisory

ATTACHMENTS / PARTS

W-161

Models Affected: All 50"/54" Decks

Serial Number Range Affected: 2004 - 2009 Model Years

Date: **December 02, 2009**

Subject: **50"/54" Mulch Strap Kit 759-04246**

PURPOSE: The Service Kit **759-04246** can be ordered and installed to help maintain the retention of the 731-04651 Mulch Plug (not included in kit) in the mower deck.

759-04246 Service Kit Contents

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	710-3015	1	HHCS:1/4-20 x .75
2	712-04064	1	1/4-20 Nylon Flange LK Nut
3	723-0476	1	Chute Strap

Instruction sheet included with kit.




FIGURE 1

NOTE: Figures 2 and 3 on back show completed installation of 759-04246 Service Kit.

This Advisory is being released for informational purposes only.

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.

Circulate and Initial



FIGURE 2

Shows strap attached to mulch plug



FIGURE 3

Shows strap attached to hook retaining bracket